



Chrysler performs a series of validation tests to ensure your consumer electronics will function properly in your vehicle. Below are lists of validated mobile phones and iPods®, including instructions for pairing your Bluetooth®-enabled mobile phone and connecting your iPod® with your vehicle. For questions and additional help, call 1-877-855-8400.



Phone Compatibility

Uconnect™ Phone is a hands-free, voice-activated, in-vehicle communications system. It utilizes Bluetooth® technology to enable your mobile phone to connect to your vehicle without wires or a docking station, allowing you to use your phone through simple voice commands. Uconnect Phone supports many popular Bluetooth-enabled mobile phones. Performance can vary widely due to the wireless carrier, phone software level, and radio software level. Listed below are phones that have passed validation testing with specific software levels and wireless carriers.



iPod® Compatibility

Uconnect supports many iPod® models for playback and control. Listed here are iPod models that have passed validation testing.

How to Use This Guide

There are two compatibility lists: One for navigation radios and another for non-navigation radios. Identify which radio you have, either by picture or by ID shown on the lower corner of the radio faceplate, then go to the appropriate bookmark.

Non-Navigation Radios



Phone pairing guidelines

1. Press the Uconnect™ hard-key to begin.



2. Wait for the beep.
3. Say SETUP/PHONE PAIRING.
4. When prompted, after the beep, say PAIR A PHONE and follow the audible prompts.
5. You will be asked to say a four-digit PIN number which you will later need to enter into your cellular phone. You can enter any four-digit PIN number. You will not need to remember this PIN number after the initial pairing process.
6. The Uconnect system will then prompt you to begin the cellular phone pairing process on your cellular phone. Before attempting to pair phone, please see your cellular phone's user manual (Bluetooth® section) for instructions on how to complete this step.
7. For identification purposes, you will be prompted to give the Uconnect System^[1] a name for your cellular phone. Each cellular phone that is paired should be given a unique phone name.

Examples of Non-navigation radios

RES Radio



REN Radio



REQ Radio



| | | | | | | |
|--|---|--|--|--|--|--|
| Phones for vehicles without navigation radio | AT&T T-Mobile Verizon Wireless Sprint PCS Metro PCS AllTel | | | | | |
| | | | | | | |

| # | Phones | Carriers | | | | | | Phone Software Version |
|---|------------------------------|----------|--|---|---|--|--|--------------------------------|
| 1 | Apple iPhone , 3G , 3GS | √ | | | | | | 1.1.3 ; 2.1 ; 3.0 ; 3.01 ; 3.1 |
| 2 | Audiovox PPC6600/6601/VX6700 | | | √ | √ | | | 1.35.119 |
| 3 | Audiovox SMT 5600 | √ | | | | | | A10.01 |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|----|----------------------------|----------|---|---|---|---|---------------------|------------------------|
| 4 | Blackberry 7100g | √ | | | | | rel 234 (01/31/05) | |
| 5 | Blackberry 7100t | | √ | | | | 4.0.0 rel 198 | |
| 6 | Blackberry 7130c | | | | | | 4.1.0 rel 321 | |
| 7 | Blackberry 7250 | | | | √ | | 4.0.0 rel 259 | |
| 8 | Blackberry 7290 | √ | √ | | | | 4.0.0 rel 219 | |
| 9 | Blackberry 7520 iDEN | | | | | | 4.0.0 rel 319 | |
| 10 | Blackberry 8700c | √ | | | | | V 4.1.0.377 | |
| 11 | Blackberry 8700g | | | | | √ | V4.1.0.352 | |
| 12 | Blackberry 8703c | √ | | √ | | √ | V4.1.0.352 | |
| 13 | Blackberry 8800 | √ | | | | | Blackberry 8800 4.2 | |
| 14 | Blackberry 8830 | | | √ | | | 4.5.0.138 | |
| 15 | Blackberry 8900 | | √ | | | | 4.6.1.114 | |
| 16 | Blackberry Bold | √ | | | | | 4.0.147 | |
| 17 | Blackberry Curve 8300 | √ | | | | | 4.2.2.89 | |
| 18 | Blackberry Curve 8320 | | √ | | | | V 4.2.2.180 | |
| 19 | Blackberry Pearl 8100 | | √ | | | | 4.2.0.64 | |
| 20 | Blackberry Pearl 8110 | √ | | | | | 4.5.0.69 | |
| 21 | Blackberry Pearl 8120 | √ | √ | | | | 4.5.0.110 | |
| 22 | Blackberry Pearl 8130 | | | √ | √ | √ | v4.3.0.81 | |
| 23 | Blackberry Pearl Flip 8220 | | √ | | | | 4.1.0.61 | |
| 24 | Blackberry Pearl Flip 8230 | | | √ | | √ | 4.6.1.182 | |
| 25 | Blackberry Storm | | | √ | | | 4.7.0.75 | |
| 26 | Blackberry Tour | | | √ | | | 4.7 | |
| 27 | Helio Fin | | | √ | √ | | | |
| 28 | HTC 2125 | √ | | | | | | |
| 29 | HTC 8125 | √ | | | | | 2.25.11.1 | |
| 30 | HTC Diamond | | | | √ | | | |
| 31 | HTC Fuse | √ | | | | | 5.2.19568 | |
| 32 | HTC MDA | | √ | | | | | |
| 33 | HTC Mogul | | | | √ | | 2.09.654.Touch | |
| 34 | HTC P4350 | √ | √ | | | | | |
| 35 | HTC PPC 6600/6601 | | | | √ | | | |
| 36 | HTC PPC 6700 | | | | √ | | | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|----|--------------------|----------|---|---|---|---|-------------------|------------------------|
| 37 | HTC SDA | | √ | | | | | |
| 38 | HTC Shadow | √ | √ | | | | | |
| 39 | HTC Shift | √ | √ | | | | | |
| 40 | HTC Snap | | | | √ | | Blv 0.95.00a | |
| 41 | HTC Touch Diamond | √ | √ | | | | 5.2.09588 | |
| 42 | HTC Touch Pro | | | √ | √ | | 1.2.34074 | |
| 43 | HTC XV 6600 | | | | | | | |
| 44 | Kyocera KX21 CDMA | | | | | √ | | |
| 45 | Kyocera KX5 | | | | | √ | JC1.0.06 | |
| 46 | LG 355 CDMA | | | | | √ | T35ATV01 | |
| 47 | LG 600G | √ | | | | | V09A | |
| 48 | LG AX 300 | | | √ | | | T30ZATV02 | |
| 49 | LG AX 565 | | | | √ | | | |
| 50 | LG AX 830 | | | | | √ | | |
| 51 | LG AX245 | | | | | √ | TA24AC06 | |
| 52 | LG CE 110 | √ | | | | | | |
| 53 | LG CF 360 | √ | | | | | CF360-V09f | |
| 54 | LG CU 515 | √ | | | | | | |
| 55 | LG CU500 | √ | | | | | MSM32701001 | |
| 56 | LG Dare | | | √ | | | VX9700V01 | |
| 57 | LG enV 2 (vx 9100) | | | √ | | | VX910V02 | |
| 58 | LG enV3 | | | | | | VX920V02 | |
| 59 | LG Glance | | | √ | | | VX710V01 | |
| 60 | LG Incite | | √ | | | | V07p | |
| 61 | LG Invision | √ | | | | | V10a-JUN-14 | |
| 62 | LG KF 700 | √ | √ | | | | KF700V100 | |
| 63 | LG LX150 | | | | √ | | LX150V03 | |
| 64 | LG Neon | √ | | | | | GT 365-V10c-Apr10 | |
| 65 | LG Neon | √ | | | | | V10g | |
| 66 | LG PM325 | | | | √ | | PM325V16 | |
| 67 | LG Rhythm | | | | | √ | T56ATV01 | |
| 68 | LG Rumor 2 | | | | | √ | | |
| 69 | LG Scoop | | | | | √ | T26ATV01 | |
| 70 | LG Shine CU 720 | √ | | | | | Mcm4090t-V08c | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|---------------------|----------|---|---|--|--|---|-------------------------------|
| 71 | LG Trax | √ | | | | | | 1 |
| 72 | LG Versa | | | √ | | | | VX960V03 |
| 73 | LG Vu | | | √ | | | | V10H-FEB-05 |
| 74 | LG VX 10000 Voyager | | | √ | | | | VX10KV02 |
| 75 | LG VX 5400 | | | √ | | | | |
| 76 | LG VX 8350 | | | √ | | | | VX835V02 |
| 77 | LG VX 8360 | | | √ | | | | vv |
| 78 | LG VX 8560 | | | √ | | | | Vx8560V01 |
| 79 | LG VX 8610 | | | √ | | | | VX861V01 |
| 80 | LG VX 8700 | | | √ | | | | T87VZB02 |
| 81 | LG VX 8800 Venus | | | √ | | | | VX880V01 |
| 82 | LG VX 9400 | | | √ | | | | T94VZB01 |
| 83 | LG VX8100 | | | √ | | | | T81VZ04 |
| 84 | LG VX8300 | | | √ | | | | T83VZB02 |
| 85 | LG VX8500-Chocolate | | | √ | | | | T85VZB02 |
| 86 | LG VX8600 | | | √ | | | | T86VZV02 |
| 87 | LG VX9800 | | | √ | | | | T98VZV04 |
| 88 | LG VX9900 | | | √ | | | | T99VZV01 |
| 89 | LG Xenon | √ | | | | | | GR500-V10f-MAR-04-2009-ATT-US |
| 90 | Motorazr 2 V9 | √ | √ | | | | | R26331M_U_9C.13.37R_1 |
| 91 | Motorola A630 | √ | √ | | | | | A630_G_0B.81.37R |
| 92 | Motorola E398 | | | | | | | R372_G_0E.20.9 5R_A |
| 93 | Motorola E815 | | | √ | | | | 8720_01.17.03 |
| 94 | Motorola Evoke | | | | | | √ | HALOC9_01.40.01P |
| 95 | Motorola Hint | | | | | | √ | rasp4_00.21.02p |
| 96 | Motorola i580 | | | | | | | R5C.00.01 |
| 97 | Motorola i605 | | | | | | | FS2Fv00.23 |
| 98 | Motorola KRZR K1 | | √ | | | | | R452F_G_08.05.05R |
| 99 | Motorola KRZR K1 | √ | | | | | | R452F_G_08.05.05R |
| 100 | Motorola KRZR K1 | | | | | | √ | 24.0_00.24.00 |
| 101 | Motorola L2 | √ | | | | | | R3517_G_0A.63.42I |
| 102 | Motorola PEBL V6 | | √ | | | | | R478_G_08.83.76R_A |
| 103 | Motorola Q | | | | | | √ | Q2-BP_C_06.0C.02P |
| 104 | Motorola Q | | | √ | | | | Q2-BP_C_06.06.00R |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|--------------------------|----------|---|---|--|---|----------------------------|------------------------|
| 105 | Motorola Q11 | √ | √ | | | | R4W811_G_01.00.49R-01_R1 | |
| 106 | Motorola Q9C | | | √ | | | PB C03.3.20.2FP | |
| 107 | Motorola Q9M | | | √ | | | | |
| 108 | Motorola Q9N | | | √ | | | NL-BP_C_03.3D.00R | |
| 109 | Motorola RAZR V3 | √ | | | | | R374_G_0E.40.3DR | |
| 110 | Motorola RAZR V3c | | | √ | | | GATW_01.0F.02 | |
| 111 | Motorola RAZR V3c | | | | | √ | GATW_03.03.00R | |
| 112 | Motorola Razr V3m | | | √ | | | | |
| 113 | Motorola ROKR | √ | | | | | R373_G_0E.30.34R_A | |
| 114 | Motorola SLVR V7 | √ | | | | | R4513_G_08.B7.DBR_RB | |
| 115 | Motorola V360/V330 | | √ | | | | R4513_G_08.B7.86R | |
| 116 | Motorola V500/V525 | | | | | | TRIPLETS_G_0B.08.8F5R_VA | |
| 117 | Motorola V505/V80 | | | | | | | |
| 118 | Motorola V551 | √ | √ | | | | R472_G_08.18.16R_0A | |
| 119 | Motorola V557 | √ | √ | | | | R4512_G_08.28.3DR_A3 | |
| 120 | Motorola V600 | √ | √ | | | | TRIPLETS_G_0B.09.3AR_A | |
| 121 | Motorola V635 | | | | | | R474_G_08_48.90R_01 | |
| 122 | Motorola V710 | | | √ | | | 8700_01.40.0R | |
| 123 | Motorola V9M | | | | | √ | | |
| 124 | Motorola VE20 | | | | | √ | Vegas 4_00.3D.00R | |
| 125 | Motorola VE465 | | | | | √ | FROST4_00.3D.01O | |
| 126 | Motorola Z6M | | | | | √ | | |
| 127 | Nokia 1606 | | | | | √ | VP6.01 | |
| 128 | Nokia 2366i | | | √ | | | PR110b07 RM-115 | |
| 129 | Nokia 2600 | √ | | | | | VP6.03 | |
| 130 | Nokia 2605 Mirage | | | √ | | | ST_3010T_VZW_107 | |
| 131 | Nokia 2680 | | √ | | | | | |
| 132 | Nokia 2680 Slide | | √ | | | | V05.28 | |
| 133 | Nokia 2760 | | √ | | | | pt06w47_08w12_fam19_03_08 | |
| 134 | Nokia 3230 | | | | | | V4.0526.2ch 16-08-05 RM-51 | |
| 135 | Nokia 3555 | | √ | | | | | |
| 136 | Nokia 3606 | | | | | √ | DS_4051B_001_GEN | |
| 137 | Nokia 3620/3650/3660 | √ | | | | | V2.54 02/03/2003 NHL-8 | |
| 138 | Nokia 5220 Express music | √ | √ | | | | VP SX.3.9 | |
| 139 | Nokia 5300 | | X | | | | | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|-------------------------|----------|---|---|--|---|-------------------------------|------------------------|
| 140 | Nokia 6085 | √ | | | | | V.04.29 | |
| 141 | Nokia 6102i | √ | | | | | V04.63 01-03-06 RM162 | |
| 142 | Nokia 6165i | | | | | | V AZ125C0008.nep 02-03-06 | |
| 143 | Nokia 6205 | | | √ | | | BL_3034T01_VZW_188 | |
| 144 | Nokia 6230 | √ | | | | | V04.43 24-08-04 RH-28 | |
| 145 | Nokia 6230i | | | | | | 03.62 RM-72 | |
| 146 | Nokia 6255i | | | | | √ | V N100V2300.nep 14-09-05 | |
| 147 | Nokia 6265i | | | √ | | | V HL100b29.nep 08-03-06 | |
| 148 | Nokia 6275i | | | √ | | | BL100_05w21_58_05 RM154 | |
| 149 | Nokia 6288 | √ | √ | | | | V 06.10 | |
| 150 | Nokia 6310i | √ | | | | | V5.10 09/11/02 NPL-1 | |
| 151 | Nokia 6315i | | | √ | | | D6315VEM04_0.169 | |
| 152 | Nokia 6555 | √ | | | | | Vp gr06w47_07w08 | |
| 153 | Nokia 6650 | √ | | | | | V 03.10 | |
| 154 | Nokia 6820/6810 | √ | | | | | V 3.92 04-02-04 RH-26 | |
| 155 | Nokia 6822b | √ | | | | | V 4.48 11-03-05 RM-68 | |
| 156 | Nokia 7205 | | | √ | | | DR_3019T_VZW | |
| 157 | Nokia 7280 | | | | | | V03.27 14-02-05 RM-14 | |
| 158 | Nokia 7510 Supernova | √ | √ | | | | VP js08w11_08w34 | |
| 159 | Nokia 8600 Luna | | | | | | | |
| 160 | Nokia 8801 | | √ | | | | V03.04 31-01-06 RM-33 | |
| 161 | Nokia 9300 | | √ | | | | | |
| 162 | Nokia 9500 Communicator | | | | | | V04.44(01) 10/27/2004 RA-2 | |
| 163 | Nokia E50 | √ | √ | | | | V07.36.0.0 | |
| 164 | Nokia E62 | √ | | | | | 2.0618.06.17 | |
| 165 | Nokia E71 | √ | | | | | V02.36 | |
| 166 | Nokia E75 | √ | | | | | 100.48.78 | |
| 167 | Nokia Mural 6750 | √ | | | | | V 4.89 | |
| 168 | Nokia N70 | | | | | | V 3.0614.0.1 31-02-2006 RM-92 | |
| 169 | Nokia N75 | √ | | | | | 10.1.273 | |
| 170 | Nokia N78 | √ | √ | | | | V 05.214. | |
| 171 | Nokia N80 | | | | | | V 3.0614.0.1 31-03-2006 RM-92 | |
| 172 | Nokia N85 | √ | √ | | | | 10.02RD | |
| 173 | Nokia N95 | √ | √ | | | | v10.0.018 | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|----------------------|----------|---|---|---|---|----------------------------|------------------------|
| 174 | Nokia N-Gage | √ | | | | | V3.42 18-09-2003 NEM-4 | |
| 175 | Nokia N-Gage QD | √ | | | | | V 4.00 | |
| 176 | Nokia Surge | √ | | | | | | |
| 177 | Nokia Twist 7750 | | | √ | | | VN_3022T_VZW_111 | |
| 178 | Palm Centro 685 | √ | | | | | | |
| 179 | Palm Pre | | | | √ | | 1.02 | |
| 180 | Palm Treo 800W | | | | √ | | 0.1 Sprint FW 116 | |
| 181 | Palm Treo Pro | | | | √ | √ | 1.06.01 | |
| 182 | Pantech 520 | √ | | | | | IQUS0812172007 | |
| 183 | Pantech C610 | √ | | | | | IRUS05122008 | |
| 184 | Pantech C740 | √ | | | | | ISUS06232008 | |
| 185 | Samsung A870 | | | √ | | | | |
| 186 | Samsung A900 | | | | √ | | ZH21 | |
| 187 | Samsung A900(MIUI) | | | | √ | | ZF17 | |
| 188 | Samsung A930 | | | √ | | | | |
| 189 | Samsung A990 | | | √ | | | | |
| 190 | Samsung BlackJack | √ | | | | | I607UCFJE | |
| 191 | Samsung Comeback | | √ | | | | T559UVIF9 | |
| 192 | Samsung Delve | | | | | √ | V. R800. BI25 | |
| 193 | Samsung Drift | | | | √ | √ | PA503 ZJ23 | |
| 194 | Samsung Eternity | √ | | | | | A867UCID2 | |
| 195 | Samsung Exclaim M550 | | | | √ | | ES.M550 CC05 | |
| 196 | Samsung Freeform | | | | √ | | R351.CF29 | |
| 197 | Samsung Gravity 2 | | √ | | √ | | T469UVIE6 T469.003 | |
| 198 | Samsung Heat | | | | √ | √ | VP030 AB03 | |
| 199 | Samsung Highlight | | | | | | T749UVID2 | |
| 200 | Samsung i730 | | | √ | | | YE05 | |
| 201 | Samsung i830 | | | | √ | | i830.12 S.ZF15 BT: 2.08.03 | |
| 202 | Samsung Impression | √ | | | | | A877UCID3 | |
| 203 | Samsung Instict S30 | | | √ | | | ES.M810 CB23 | |
| 204 | Samsung Jack | √ | | | | | i637UCIE1 | |
| 205 | Samsung Juke | | | √ | | | | |
| 206 | Samsung M 520 | | | | √ | | BA23 | |
| 207 | Samsung M220 | | | | √ | | M220 BF06 | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|----------------------|----------|---|---|---|--|---|------------------------|
| 208 | Samsung M300 | | | | √ | | | S:M300 AC06 |
| 209 | Samsung M320 | | | | √ | | | M320 BF06 |
| 210 | Samsung M330 | | | | √ | | | ES.M330 CE30 |
| 211 | Samsung M500 | | | | √ | | | S:ES.M500 ZK03 |
| 212 | Samsung M540 | | | | √ | | | ES.M540 Bi04 |
| 213 | Samsung M610 | | | | √ | | | ZJ01 |
| 214 | Samsung M620 | | | | √ | | | AC 21 |
| 215 | Samsung M630 | | | | √ | | | B104 |
| 216 | Samsung Magnet | √ | | | | | | |
| 217 | Samsung Mantra | | | | | | | M340CB13 |
| 218 | Samsung Memoir | | √ | | | | | T929UVIA2 |
| 219 | Samsung Mysto | | | | | | | PA523 AI 130 |
| 220 | Samsung Ommnia | | | √ | | | | VZV0.1 |
| 221 | Samsung Propel Pro | √ | | | | | | I627UCIC2 |
| 222 | Samsung R430 | | | | | | √ | R430.BB15 |
| 223 | Samsung R510 | | | | | | √ | R510.ZL01 |
| 224 | Samsung R600 | | | | | | √ | R600.B07 |
| 225 | Samsung Reclaim | | | | √ | | | M560.CF01 |
| 226 | Samsung SCH i325 | | | | √ | | | AL 16 |
| 227 | Samsung SCH i760 | | | √ | | | | 5.2.979 |
| 228 | Samsung SGH a717 | √ | | | | | | A717UCGD6P |
| 229 | Samsung SGH a727 | √ | | | | | | A727UCGD5OK |
| 230 | Samsung SGH F700 | √ | √ | | | | | 128.bvs.3_1 |
| 231 | Samsung SGH T239 | | √ | | | | | GT239.00T239UVIA2 |
| 232 | Samsung SGH T349 | | √ | | | | | ET349.02 T349UVIC3 |
| 233 | Samsung Soltice | √ | | | | | | A887UCIE4 |
| 234 | Samsung SPH M800 | | | | √ | | | BC25 |
| 235 | Samsung U420 | | | | | | √ | U420.ZF29 |
| 236 | Samsung U520 | | | | | | √ | U520.AC 31 |
| 237 | Samsung u706 | | | | | | √ | BC 04 |
| 238 | Samsung Z400 | | | | √ | | | BA21 |
| 239 | Samsung Z700 | | | | √ | | | AL16 |
| 240 | Sanyo Katana DLX | | | | √ | | | 1.002SP |
| 241 | Sanyo Katana Eclipse | | | | √ | | | 1002SP |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|---------------------------|----------|---|--|---|--|------------------------------------|------------------------|
| 242 | Sanyo Katana II | | | | √ | | 1.004SP | |
| 243 | Sanyo Katana LX | | | | √ | | 1.002 SP | |
| 244 | Sanyo M1 | | | | √ | | 0.206SP | |
| 245 | Sanyo pro 200 | | | | √ | | | |
| 246 | Sanyo Pro 700 | | | | √ | | 0.600SP | |
| 247 | Sanyo S1 | | | | √ | | 0.500 sp | |
| 248 | Sanyo SCP 2700 | | | | √ | | 0.900SP | |
| 249 | Sanyo SCP 3200 | | | | √ | | 1.000SP | |
| 250 | Sanyo SCP-6600 (Katana) | | | | √ | | 1.000SP | |
| 251 | Sanyo SCP-7050 | | | | √ | | 0.300SP | |
| 252 | Sanyo SCP-8400 | | | | √ | | V1.002 | |
| 253 | Siemens S55/S56 | √ | | | | | 11 2003-01-06 | |
| 254 | Siemens S65/S66 | √ | | | | | 34 2004-11-12 | |
| 255 | Sony Ericsson C905a | √ | | | | | R1BA037 | |
| 256 | Sony Ericsson G502 | √ | √ | | | | R1FA031 | |
| 257 | Sony Ericsson K700i/K750i | √ | | | | | R1A044 (K750i) | |
| 258 | Sony Ericsson K850i | √ | | | | | | |
| 259 | Sony Ericsson S500i | √ | | | | | | |
| 260 | Sony Ericsson S700i/S710a | √ | | | | | R 1A033 (S710a) | |
| 261 | Sony Ericsson T610 | √ | √ | | | | prgCXC12-5600_US_3 | |
| 262 | Sony Ericsson T616/T637 | √ | | | | | R 1A054 | |
| 263 | Sony Ericsson W300i | √ | | | | | R4EA031 | |
| 264 | Sony Ericsson W350 | √ | √ | | | | R4CF044 | |
| 265 | Sony Ericsson W518a | √ | | | | | R1EB009 prg1218-6174_ATT_BRR1EB009 | |
| 266 | Sony Ericsson W580i | √ | | | | | | |
| 267 | Sony Ericsson W600i | √ | | | | | R7B046 | |
| 268 | Sony Ericsson W760 | √ | | | | | R3BA035 | |
| 269 | Sony Ericsson W810i | √ | | | | | R4CF002 | |
| 270 | Sony Ericsson Z520a | √ | | | | | R3C042 | |
| 271 | Sony Ericsson Z600 | | √ | | | | R2E004 | |
| 272 | Sony Ericsson Z750 | √ | | | | | | |

Phones for vehicles
without navigation
radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|-----|---------------------|----------|---|---|---|--|---|-----------------------------|
| 273 | Sony Ericsson Z780a | √ | | | | | | R3BA035 |
| 274 | T Mobile G1 | | √ | | | | | 62.33.20.08H_1.22.12..29 |
| 275 | Tmobile Dash | | √ | | | | | 1.22.531.6 |
| 276 | Toshiba G500 | √ | √ | | | | | 03.04AAI |
| 277 | Treo 650 | | | | √ | | | Treo650-1.13-SPCS |
| 278 | Treo 650 | | | | | | √ | Treo650-1.03-CDMA |
| 279 | Treo 680 | √ | | | | | | 5.2 H |
| 280 | Treo 700P | | | | | | √ | Treo700P-1.40-CDMA |
| 281 | Treo 700P | | | | √ | | | Treo700P-/1226/108 |
| 282 | Treo 700W | | | √ | | | | Treo700W-1.10-VZW |
| 283 | Treo 700WX | | | | | | √ | Treo700wx-1.10-ROWEN |
| 284 | Treo 750V | √ | | | | | | Build 604/ HTC Version 0.96 |
| 285 | Treo 755P | | | | √ | | | Treo755p-/6020/159 |
| 286 | Treo Centro | | | | √ | | | |



Navigation Radios

Phone Pairing Guidelines

1. Press the MENU hard-key on the right side of the radio
2. Then touch the System Setup soft-key to get to the System Setup menu.
3. Touch the Phone Pairing soft-key to access the Bluetooth® Devices menu. This menu lists all paired Bluetooth devices
4. Press the PAIR soft-key to start a new pairing.
5. Enter any 4 Digit Security PIN and touch the PAIR soft-key again.
6. The pairing procedure starts. Refer to the user's manual of your Bluetooth phone to complete the procedure.
7. You will then be asked to set a priority for the paired phone. If there is more than one paired phone available, the navigation radio will try to connect to the phone with the highest priority setting.

REU Radio



RER Radio



Phones for vehicles with navigation radio

AT&T
T-Mobile
Verizon Wireless
Sprint PCS
Metro PCS
AllTel

| # | Phones | Carriers | | | | | | Phone Software Version |
|----|------------------------------|----------|---|---|---|--|--|---|
| 1 | Apple Iphone 3G | ✓ | | | | | | 1.13 2.0.2 (5c1) 3.0 |
| 2 | Audiovox PPC6600/6601/VX6700 | | | | | | | |
| 3 | Audiovox SMT 5600 | | | | | | | |
| 4 | Blackberry 7100g | | | | | | | |
| 5 | Blackberry 7100t | | | | | | | |
| 6 | Blackberry 7130c | | | | | | | |
| 7 | Blackberry 7250 | | ✓ | | ✓ | | | 4.1 |
| 8 | Blackberry 7290 | ✓ | ✓ | | | | | 4.0.2 |
| 9 | Blackberry 7520 | | | | | | | |
| 10 | Blackberry 8100 | ✓ | | | | | | V4.2.1.96 |
| 11 | Blackberry 8700c | ✓ | | | | | | V4.2.1.96 |
| 12 | Blackberry 8830 | | | | ✓ | | | v4.2.2.123 (Platform 3.0.0.64) |
| 13 | Blackberry 8830 | | | ✓ | | | | V4.2.2.196 |
| 14 | Blackberry Pearl 8120 | ✓ | | | | | | V4.3.0.91 |
| 15 | Blackberry Pearl 8130 | | | | ✓ | | | v4.3.0.71 (Platform 3.1.0.37) |
| 16 | HTC 8125 | | | | | | | |
| 17 | HTC Mogul PPC6800 | | | | ✓ | | | HTC Mogul PPC6800 |
| 18 | HTC Touch Pro | | | | ✓ | | | 1.03.15F |
| 19 | Kyocera KX5 | | | | | | | |
| 20 | LG 355 | | | | | | | |
| 21 | LG CE110 | ✓ | | | | | | V10g |
| 22 | LG Chocolate 3 VX-8560 | | | ✓ | | | | VX856V05 |
| 23 | LG Chocolate VX8500 | | | ✓ | | | | T85V2G06 |
| 24 | LG CU515 | ✓ | | | | | | CU515-MSM21302430-V10G-NOV-27-2008-ATT-US |
| 25 | LG Dare VX-9700 | | | ✓ | | | | VX970V03 |
| 26 | LG Decoy VX-8610 | | | ✓ | | | | VX861V01 |
| 27 | LG Lotus | | | | ✓ | | | LX600V07 |
| 28 | LG LX 280 | | | | ✓ | | | LX280V0a |
| 29 | LG LX150 | | | | | | | |
| 30 | LG Muziq/AX-565/UX-565 | | | | ✓ | | | LX570V05 |
| 31 | LG PM325 | | | | | | | |
| 32 | LG Rumor/Scoop/UX-260 | | | | ✓ | | | LX260V06 |
| 33 | LG VX 10000 | | | ✓ | | | | VX10KV07 |
| 34 | LG VX 8550 | | | ✓ | | | | VX855V03 |

| | | | | | | | | |
|----|--------------------------|---|---|---|--|---|--|---|
| 35 | LG VX 8600 | | | ✓ | | | | T86VZV02 |
| 36 | LG VX 8600 | | | ✓ | | | | T86VZV02 |
| 37 | LG VX 8800 | | | ✓ | | | | VX880V01 |
| 38 | LG VX 8800 | | | ✓ | | | | VX880V03 |
| 39 | LG VX 9100 | | | ✓ | | | | VX910V02 |
| 40 | LG VX10000 (Voyager) | | | ✓ | | | | VX10KV07 |
| 41 | LG VX5400 | | | ✓ | | | | VX540V01 |
| 42 | LG VX8100 | | | ✓ | | | | T81VZV04 |
| 43 | LG VX8300 | | | ✓ | | | | T83VZV01 |
| 44 | LG VX8300 | | | ✓ | | | | T83V2V03 |
| 45 | LG VX8350 | | | ✓ | | | | VX835V02 |
| 46 | LG VX8500-Chocolate | | | ✓ | | | | T85VZV03 |
| 47 | LG VX8550- New Chocolate | | | ✓ | | | | VX855V01 |
| 48 | LG VX8700 | | | ✓ | | | | T87VZV03 |
| 49 | LG VX9100 (enV2) | | | ✓ | | | | VX9100V04 |
| 50 | LG VX-9400 | | | ✓ | | | | T9MVZ03 |
| 51 | LG VX9800 | | | | | | | |
| 52 | Motorola A630 | | | | | | | |
| 53 | Motorola Adventure V750 | | | ✓ | | | | CHARL1_01.30.10P |
| 54 | Motorola E398 | | | | | | | |
| 55 | Motorola E815 | | | | | | | |
| 56 | Motorola i580 | | | | | | | |
| 57 | Motorola i605 | | | | | | | |
| 58 | Motorola i880 | | | | | ✓ | | FS6Ev00.29 |
| 59 | Motorola K1m | | | ✓ | | | | 24.1_00.25.0C |
| 60 | Motorola Krave ZN4 | | | ✓ | | | | BLAZE1_01.19.0AP |
| 61 | Motorola KRZR K1m | | | ✓ | | | | Motorola KRZR K1m |
| 62 | Motorola L2 | | ✓ | | | | | |
| 63 | Motorola L2 | | ✓ | | | | | R3511_G_0A.53.15R |
| 64 | Motorola L7 | | ✓ | | | | | |
| 65 | Motorola PEBL V6 | | ✓ | | | | | R478_G_08.83.76R_A |
| 66 | Motorola Q | | | | | | | |
| 67 | Motorola Q | | | ✓ | | | | Q2-BP_C06.0B.13P |
| 68 | Motorola Q9 | | | ✓ | | | | TRPLT2_02.68.00R |
| 69 | Motorola Q9c | | | | | ✓ | | NL-BP_C_03.33.01P MP_BSP_C.04.09.01- 02P_N_P3.0 |
| 70 | Motorola Q9m | | | ✓ | | | | NL-BP_C_03.20.29P, MP_BSP_C_04.08.65- 15P_NM_P3.0 |
| 71 | Motorola Rapture VU30 | | | ✓ | | | | CHARL1_01.30.06P |
| 72 | Motorola RAZR maxx Ve | | | ✓ | | | | 20.1_01.36.06 |
| 73 | Motorola RAZR V3 | ✓ | ✓ | | | | | R374_G_0E.42.10R_A |
| 74 | Motorola RAZR V3c | | | ✓ | | | | GATW_01.0F.02 |
| 75 | Motorola RAZR V3m | | | | | | | |

| | | | | | | | | |
|-----|-------------------------|---|---|---|--|--|--|--------------------------|
| 76 | Motorola RAZR V3xx | ✓ | | | | | | R26111LD_U_96.71.95R |
| 77 | Motorola RAZR2 V9m | | | ✓ | | | | Motorola RAZR2 V9m |
| 78 | Motorola ROKR | | | | | | | |
| 79 | Motorola SLVR V7 | ✓ | | | | | | R3511_G_0A.52.31R_B |
| 80 | Motorola V3 | ✓ | | | | | | R374_G_0E.41.C3R_B |
| 81 | Motorola V360/V330 | | | | | | | |
| 82 | Motorola V3t | | ✓ | | | | | R3443U5_G_0E.C8.0DR |
| 83 | Motorola V3xx | ✓ | | | | | | R26111MLD_AS_U_96.B0.0FR |
| 84 | Motorola V500/V525 | | | | | | | |
| 85 | Motorola V505/V80 | | | | | | | |
| 86 | Motorola V551 | ✓ | | | | | | 08.18.16R_0A7 |
| 87 | Motorola V557 | ✓ | ✓ | | | | | R4512_G_08.28.3DR_A3 |
| 88 | Motorola V600 | ✓ | | | | | | |
| 89 | Motorola V635 | | | | | | | |
| 90 | Motorola V710 | | | ✓ | | | | 8700_01.40.0R |
| 91 | Motorola V9 | ✓ | | | | | | |
| 92 | Motorola W755 | | | ✓ | | | | C00L01_00.30.08P |
| 93 | Motorola Z6c | | | ✓ | | | | JACQUE_0.1.30.11P |
| 94 | Nokia 2366i | | | | | | | |
| 95 | Nokia 3230 | | | | | | | |
| 96 | Nokia 3620/3650/3660 | | | | | | | |
| 97 | Nokia 6102i | | | | | | | |
| 98 | Nokia 6126 | ✓ | | | | | | 4.28 |
| 99 | Nokia 6133 | | ✓ | | | | | V05.60 |
| 100 | Nokia 6165i | | | | | | | |
| 101 | Nokia 6205 | | | ✓ | | | | BL_4047T12_VZW_203 |
| 102 | Nokia 6230 | | ✓ | | | | | 05.50 |
| 103 | Nokia 6230i | | | | | | | |
| 104 | Nokia 6255i | | | | | | | |
| 105 | Nokia 6265i | | | | | | | |
| 106 | Nokia 6275i | | | | | | | |
| 107 | Nokia 6310i | ✓ | | | | | | 5.5 |
| 108 | Nokia 6315i | | | | | | | |
| 109 | Nokia 6555b | ✓ | | | | | | V03.31 01-08-07 RM-289 |
| 110 | Nokia 6820/6810 | | | | | | | |
| 111 | Nokia 6822b | | | | | | | |
| 112 | Nokia 7280 | | | | | | | |
| 113 | Nokia 8801 | | | | | | | |
| 114 | Nokia 9500 Communicator | | | | | | | |
| 115 | Nokia E61 | | ✓ | | | | | 1.0610.04.04 |
| 116 | Nokia N70 | | | | | | | |
| 117 | Nokia N76 | ✓ | | | | | | |
| 118 | Nokia N80 | | | | | | | |
| 119 | Nokia N-Gage | | | | | | | |
| 120 | Nokia N-Gage QD | | | | | | | |

| | | | | | | | | |
|-----|----------------------------------|---|---|---|---|--|--|---------------------------|
| 121 | Palm Treo 800w | | | | ✓ | | | TREO800W-1.03-SPNT |
| 122 | Pantech Breeze C520 | ✓ | | | | | | Pantech Breeze C520 |
| 123 | Samsung A900 | | | | ✓ | | | |
| 124 | Samsung A900(MIUI) | | | | | | | |
| 125 | Samsung D407 | ✓ | | | | | | D407UCFD1 |
| 126 | Samsung Flipshot SCH-U900 | | | ✓ | | | | V.U900.AJ24 |
| 127 | Samsung Highnote M630 | | | | ✓ | | | ES.M630 BI09 |
| 128 | Samsung i730 | | | | | | | |
| 129 | Samsung i830 | | | | | | | |
| 130 | Samsung Instinct M800 | | | | ✓ | | | ES.M800 BF30 |
| 131 | Samsung Juke U470 | | | ✓ | | | | V.U470.AH23 |
| 132 | Samsung M320 | | | | ✓ | | | Samsung M320 |
| 133 | Samsung Rant M540 | | | | ✓ | | | ES.M540 BI09 |
| 134 | Samsung SCH-i760 | | | ✓ | | | | u740.ZL05 |
| 135 | Samsung SCH-U430 | | | ✓ | | | | u430.BF06 |
| 136 | Samsung SCH-U550 | | | ✓ | | | | u550.BA10 |
| 137 | Samsung SCH-U740 | | | ✓ | | | | V u740.ZL05 |
| 138 | Samsung SGH-A517 | ✓ | | | | | | A517UC665 |
| 139 | Samsung SGH-i617 | ✓ | | | | | | I617UCGK2 |
| 140 | Samsung SGH-T429 | | ✓ | | | | | Samsung SGH-T429 |
| 141 | Samsung SGH-T439 | | ✓ | | | | | ET439.07 T439UVG17 |
| 142 | Samsung SPH-A900 | | | | ✓ | | | ES.A900 AB15 |
| 143 | Samsung Sway U650 | | | ✓ | | | | u650.BI04 |
| 144 | Samsung U940 (Glyde) | | | ✓ | | | | U940.BD05 |
| 145 | Sanyo Katana II | | | | ✓ | | | 1.004SP |
| 146 | Sanyo Katana LX | | | | ✓ | | | 1.002SP |
| 147 | Sanyo M1 | | | | | | | |
| 148 | Sanyo SCP-6600 (Katana) | | | | | | | |
| 149 | Sanyo SCP-8400 | | | | | | | |
| 150 | Siemens S55/S56 | | | | | | | |
| 151 | Siemens S65/S66 | ✓ | | | | | | 34 |
| 152 | Sony Ericsson K700i/K750i | | | | | | | |
| 153 | Sony Ericsson S700i/S710a | | | | | | | |
| 154 | Sony Ericsson T610 | | ✓ | | | | | R1L013 prgCXC12-5570_US_1 |
| 155 | Sony Ericsson T616/T637 | ✓ | | | | | | R3A027 |
| 156 | Sony Ericsson W600i | ✓ | | | | | | R7B046 |
| 157 | Sony Ericsson W810i | | | | | | | |
| 158 | Sony Ericsson Z520a | | | | | | | |
| 159 | Sony Ericsson Z600 | | | | | | | |
| 160 | Treo 650 | ✓ | | | | | | 5.2H |
| 161 | Treo 650 | | | ✓ | | | | v.5.2H |
| 162 | Treo 700W | | | | | | | |
| 163 | Treo 750V | | | | | | | |
| 164 | VX8800 Venus | | | ✓ | | | | VX8802 |



iPod® Compatibility

Plug your iPod® into the custom cable located in the glove box or center console. With this "plug and play" hook up you can control your iPod through your radio controls.

Non-Navigation Radios^[2]

| iPod® Model | Generations Supported | iPod® generations that require the new interface cable for vehicle charging |
|---------------|----------------------------|---|
| iPod classic® | 4th, 5th and 6th | 6th |
| mini | 1st and 2nd | |
| iPod nano® | 1st, 2nd, 3rd, 4th and 5th | 4th & 5th |
| iPod touch® | 1st, 2nd and 3rd | 2nd & 3rd |
| iPhone® | Original, 3G and 3Gs | 3G & 3Gs |

Navigation Radios*

| iPod® Model | Generations Supported |
|---------------|-----------------------|
| iPod classic® | 4th, 5th and 6th |
| iPod nano® | 1st, 2nd, 3rd, 4th |
| iPod touch® | 1st, 2nd |

1 Uconnect in-dash DVD capability is not available in all states. See your dealer for details.

2 iPod shuffle® is not supported.

3 Some iPods and iPhones will not charge with the factory supplied interface cable. A new interface cable is available that will allow all iPods to charge from the vehicle. The new cable is available through your dealer.

iPod is a registered trademark of Apple, Inc.

iPod nano is a registered trademark of Apple, Inc.

iPod touch is a registered trademark of Apple, Inc.

iPod classic is a registered trademark of Apple, Inc.
iPhone is a registered trademark of Apple, Inc.
iPod shuffle is a registered trademark of Apple, Inc.
Bluetooth is a registered trademark of Bluetooth SIG, Inc.

Last Update: 12/15/09
Version: 5